

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt Governor

Kathleen Clarke Executive Director

Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax)

801-538-7223 (TDD)

Partial: XXX Complete:

te: Exploration:

Inspection Date & Time: 10:00a.m.-2:00p.m.

Date of Last Inspection: 10/20/2000

Mine Name: Horizon Mine	County: Carbon	Permit Number: _A	CT9697/4/20
Permittee and/or Operator's Name: _	Lodestar Energy, Inc.		
Business Address: <u>HC 35 Box 37</u>	0, Helper, Utah 84526		<u> </u>
Type of Mining Activity: Undergrou	und XXX Surface	Prep. Plant	Other
Company Official(s): Rich Richie			
State Official(s): Bill Malencik	Federal Official(s): None		
Weather Conditions: Snowing, 5":			
Existing Acreage: Permitted 317		graded Se	
Status: Exploration Active _>	XXX Inactive Tem	porary Cessation	Bond Forfeiture
Reclamation (Phase I	Phase II Final Bond Rel	leaseLiability _	Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	<u>N/A</u>	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	<u>[X]</u>	$\overline{\Box}$	П	\Box
3.	TOPSOIL	[X]	\Box	П	\Box
4.	HYDROLOGIC BALANCE:	-			,
	a. DIVERSIONS	[X]		[X]	\Box
	b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]	Ш	[X]	\Box
	c. OTHER SEDIMENT CONTROL MEASURES	[X]	П	[X]	\Box
	d. WATER MONITORING		\Box		\Box
	e. EFFLUENT LIMITATIONS	\Box	\Box		
5.	EXPLOSIVES	\Box	\Box	П	
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	\Box	П	П	\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	\Box	[X]	\Box
8.	NONCOAL WASTE	[X]	П		\Box
9.	PROTECTION OF FISH, WILDLIFE AND RELATED		\Box		\Box
	ENVIRONMENTAL ISSUES				
	SLIDES AND OTHER DAMAGE	П	\Box	Ц	
	CONTEMPORANEOUS RECLAMATION	\Box	П	П	П
	BACKFILLING AND GRADING			Ш	Ц
	REVEGETATION	П	\Box	П	Ц
	SUBSIDENCE CONTROL	П	П	Ц	П
	CESSATION OF OPERATIONS		П		Ц
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	[X]	Ц		Ц
	b. DRAINAGE CONTROLS	[X]	П	[X]	Ц
	OTHER TRANSPORTATION FACILITIES		П	Ц	Ц
	SUPPORT FACILITIES/UTILITY INSTALLATIONS	Ц	П	Ц	Ц
	AVS CHECK (4th Quarter- April, May, June)	Ц	Ц	Ц	Ц
	AIR QUALITY PERMIT	П	Ц	Ц	. []
21.	BONDING & INSURANCE	[]	[]	\sqcup	\Box

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/007/020

DATE OF INSPECTION: 11/9/2000

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

GENERAL COMMENTS

Performed a partial inspection of the Horizon Mine. The following things were noted at the mine.

- -The high ash coal pile is moving slowly. The mine manager informed me that they are moving a truck load periodically to White Oak mine. The pile is no different than the last inspection, as near as I can determine.
- -Mine was discharging water.
- -The mine is working with BLM on a proposed right-of-way that would accelerate the mine into production.

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permit on part of the 300+ acre federal lease is now ready for publication per notification from the Division. Checked the court house and a copy of their application is available for public review.

4A. HYDROLOGIC BALANCE: DIVERSIONS

A northerly ditch adjacent to the upper storage areas had some old belt line stored in part of the ditch. This was not in the ditch the last inspection. Mr. Richie stated he would remove the belt line and it was done at noon.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The third quarter pond inspection report was inspected and reported. The report was certified. The pond was not discharging.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The permittee replaced 25 straw bales on the disturbed area below the sediment pond.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The matter of coal mine waste has been settled with this understanding that what was referred to as coal waste is high ash coal.

16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

The county had pushed snow into the undisturbed permit area.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM
David Miller, Lodestar

Price Field office

O:\007020.HZN\Compliance\2000\p_1109.wpd